

Oil Field Environmental Incident Summary

Incident: 20140627080059

Date/Time of Notice: 06/27/2014 08:00

Responsible Party: PetroHarvester

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: EVENSON 1-R

Field Name: WAYNE

Well File #: 9091

Date Incident: 6/26/2014

Time Incident: 10:26

Facility ID Number:

County: BOTTINEAU

Twp: 162

Rng: 81

Sec: 31

Qtr: NE NW

Location Description: At Wellhead

Submitted By: Shane Jensen

Received By:

Contact Person: Ben Tohm
5160 TENNYSON PARKWAY
SUITE 3000 E
PLANO, TX 75024

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels	15	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/11/2015

Clean Up Concluded: 6/26/2014

Risk Evaluation:

No immediate risk.

Areal Extent:

Potential Environmental Impacts:

Affected soil and gravel on location.

Action Taken or Planned:

Sucked up, and absorbed all visual fluid. Fixed flowline (1").

Wastes Disposal Location: Fluid will be disposed of to SWD. Affected soil and pads will be sent to PDI (Tioga).

Agencies Involved:

Updates

Date: 6/27/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak at the wellhead, remained on location according to the report. NDIC retains oversight.